

Notification of long lead time for MCP and MCP assemblies

Dear customers,

We would like to express our thanks for your loyal patronage.

Our production building of MCP and MCP assembly will be moved to a new building in Toyooka factory.

Due to the move, lead time of some MCP and MCP assemblies become long.

Some specific MCP and MCP assemblies below would be excepted for such long lead time, so please note the situation will continue until the move is end which will be April 2024.

Please accept our apologies for the inconvenience.

Exception of long lead time (~~Updated in September 2023~~)

-MCP

F1094-011

~~F1217-01~~

F1217-011

F1551-01

F1552-011

~~-MCP assemblies~~

~~F2225-series~~

~~F9890-13~~

~~F9890-31~~

~~F13446-11~~

~~F13447-11~~

The underlined MCP and MCP assemblies which could be delivered by the end of March 2024 were sold out. Please contact from [here](#) for the purchase and delivery after April 2024.